APPENDIX A PROJECT GRAPHICS





VIEWS FROM LIFEGUARD HEADQUARTERS







DETERIORATING EXTERIOR OF EXISTING LIFEGUARD HEADQUARTERS



LOOKING UP FROM THE BEACH AT BLUFF EROSION AND LIFEGUARD HEADQUARTERS



DETERIORATION OF THE LIFEGUARD HEADQUARTERS EXTERIOR



LIFEGUARD HEADQUARTERS INTERIOR SHOWING LACK OF SPACE